



ROADWORTHY AND VEHICLE
TESTING CENTRE

GLOBAL VEHICLE COMPREHENSIVE
REPORT

Customer: EXTREME

Date: 2023-11-22 10:15

Title: Initials:

Surname:

Make: Model:

Chassis Vin:

Body Type: Colour:

Kilometers:

Engine Capacity:

No of Doors: Year:

Registration:

Transmission:

Paint Finish: Fuel Type:

Register No:

Engine No:

Last Roadworthy Date:

License Expiry Date:

Engine Compartment

Engine Number	Y	Oil	Y	Engine Mountings	Y	Brake Fluid Levels	Y
Bonnet Catch	Y	Visual Condition of Battery	Y	Picture of Engine	Y		

Right Front Driver Door

Driver Door	Y	Door Hinges	Y	Driver Door Safety Catch	Y	Windows	Y
Side Rear View Mirror	Y	Seatbelts	Y	Seat Pic	Y	Right Front CNR Pic	Y
Front right fender	Y						

Right Front Wheel

Wheel nuts	Y	Tyre Thread Pic	Y	Rims, Mags Pic	Y	Tyre Size, Type of Tyre	Y
Windscreen	Y	Windscreen Wiper	Y				

Lights

Head Lamp	Y	Indicator Lamp	Y	Fog Lamp/Spot Lamp	N/A	Park Lights	Y
Front of Vehicle Pic	Y	Front of vehicle condition	Y				

Left Front Wheel

Wheel nuts	Y	Tyre Thread Pic	Y	Rims, Mags Pic	Y	Tyre Size, Type of Tyre	Y
Windscreen	Y	Windscreen Wiper	Y				

Left Front Passenger Door

Passenger Door	Y	Door Hinges	Y	Passenger Door Safety Catch	Y	Windows	Y
Side Rear View Mirror	Y	Seatbelts	Y	Seat Pic	Y	Left Front CNR Pic	Y
Left Side Pic	Y	Front left fender	Y				

Left Rear Passenger Door

Passenger Door	Y	Door Hinges	Y	Passenger Door Safety Catch	Y	Windows	Y
Seatbelts	Y	Seat Pic	Y	Left rear quarter panel	Y		

Left Rear Wheel

Wheel nuts	Y	Tyre Thread Pic	Y	Rims, Mags Pic	Y	Tyre Size, Type of Tyre	Y
------------	---	-----------------	---	----------------	---	-------------------------	---

Rear Lights

Tail Lights	Y	Brake Lights	Y	Indicator Lights	Y	Numberplate Lights	Y
Rear Left CNR Pic	Y	Rear of Vehicle Pic	Y	Rear of vehicle condition	Y		

Trunk

Trunk Floor Mat Pic	Y	Tool Kit	N/A	Spare Wheel Pic	Y	Spare Wheel Size	Y
Spare Wheel Thread	Y						

Right Rear Wheel

Wheel nuts	Y	Tyre Thread Pic	Y	Rims, Mags Pic	Y	Tyre Size, Type of Tyre	Y
------------	---	-----------------	---	----------------	---	-------------------------	---

Right Rear Passenger Door

Passenger Door	Y	Door Hinges	Y	Passenger Door Safety Catch	Y	Windows	Y
Seatbelts	Y	Seats	Y	Right Rear CNR Pic	Y	Right Side Pic	Y
Right rear quarter panel	Y						

Dashboard & Instrumentation Cluster

Wiper	Y	Dim/Bright	Y	Speedometer	Y	Rev Counter	Y
Oil Light	Y	Battery Charge indicator	Y	Heat Gauge	Y	Fuel Gauge	Y
Dashboard	Y	Steering Wheel	Y	Dash & Cluster Pic	Y	Center Console & Hand Brake Pic	Y
Warning lights	Y						

Warning Devices

Fire Extinguisher	N/A	Warning Triangle	Y				
-------------------	-----	------------------	---	--	--	--	--

Floor Board

Floor Boards	Y	Clutch Peddle	Y	Brake Peddle	Y	Accelerator Peddle	Y
--------------	---	---------------	---	--------------	---	--------------------	---

Testing of Brakes

Service Brake Front	Y	Service Brake Rear	Y	Park/Emergency Brake	Y	Hydraulic Pipes	Y
Drive Train	Y	Brake Test Report	N/A				

Under Carriage Suspension

Drive Train	Y	CV (Inner + Outer)	Y	Steering Rack	Y	Stabilizer Bars	Y
Anti Roll Bar	Y	Cross Member	Y	Control Arms/Bushes	Y	Shock Mountings	Y

Exhaust System

Catalytic Converter	Y	Silencers	Y	Hangers	Y		
---------------------	---	-----------	---	---------	---	--	--

Diagnostic Report

Electronic Health Report	N/A	Fault Codes	N/A	Battery Check	N/A	Alternator Check	N/A
--------------------------	-----	-------------	-----	---------------	-----	------------------	-----

Summary

Engine Compartment: Picture of Engine: , Right Front Driver Door: Seat Pic: , Right Front Driver Door: Right Front CNR Pic: , Right Front Wheel: Tyre Thread Pic: , Right Front Wheel: Rims, Mags Pic: , Right Front Wheel: Windscreen: , Lights: Front of Vehicle Pic: , Left Front Wheel: Tyre Thread Pic: , Left Front Wheel: Rims, Mags Pic: , Left Front Passenger Door: Seat Pic: , Left Front Passenger Door: Left Front CNR Pic: , Left Front Passenger Door: Left Side Pic: , Left Rear Passenger Door: Seat Pic: , Left Rear Wheel: Tyre Thread Pic: , Left Rear Wheel: Rims, Mags Pic: , Rear Lights: Rear Left CNR Pic: , Rear Lights: Rear of Vehicle Pic: , Trunk: Spare Wheel Pic: , Right Rear Wheel: Tyre Thread Pic: , Right Rear Wheel: Rims, Mags Pic: , Right Rear Passenger Door: Right Rear CNR Pic: , Right Rear Passenger Door: Right Side Pic: , Dashboard & Instrumentation Cluster: Dash & Cluster Pic: , Dashboard & Instrumentation Cluster: Center Console & Hand Brake Pic:



Examiner Name & Surname	mahesh@globalvt.com
Branch	Bramley





The GVT Comprehensive Vehicle Report (GCVR) is a comprehensive functional and visual assessment of all the items listed in the report. GVT cannot be held liable for possible concealed and hidden defects. GVT doesn't check oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players, sound or radio reception, alarm systems, cylinder compression; anti theft and tracking mechanism as well as any speed enhanced non OEM features. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This GCVR is valid only for the described vehicle and the described condition at the time of inspection and remains the intellectual property of Global Vehicle Testing. GVT terms and conditions apply.

Images	Comments
	<p>Engine Compartment: Picture of Engine:</p>
	<p>Right Front Driver Door: Seat Pic:</p>
	<p>Right Front Driver Door: Right Front CNR Pic:</p>
	<p>Right Front Wheel: Tyre Thread Pic:</p>
	<p>Right Front Wheel: Rims, Mags Pic:</p>

Images	Comments
	Right Front Wheel: Windscreen:
	Lights: Front of Vehicle Pic:
	Left Front Wheel: Tyre Thread Pic:
	Left Front Wheel: Rims, Mags Pic:
	Left Front Passenger Door: Seat Pic:

Images	Comments
	<p>Left Front Passenger Door: Left Front CNR Pic:</p>
	<p>Left Front Passenger Door: Left Side Pic:</p>
	<p>Left Rear Passenger Door: Seat Pic:</p>
	<p>Left Rear Wheel: Tyre Thread Pic:</p>
	<p>Left Rear Wheel: Rims, Mags Pic:</p>

Images	Comments
	<p>Rear Lights: Rear Left CNR Pic:</p>
	<p>Rear Lights: Rear of Vehicle Pic:</p>
	<p>Trunk: Spare Wheel Pic:</p>
	<p>Right Rear Wheel: Tyre Thread Pic:</p>
	<p>Right Rear Wheel: Rims, Mags Pic:</p>

Images	Comments
	<p>Right Rear Passenger Door: Right Rear CNR Pic:</p>
	<p>Right Rear Passenger Door: Right Side Pic:</p>
	<p>Dashboard & Instrumentation Cluster: Dash & Cluster Pic:</p>
	<p>Dashboard & Instrumentation Cluster: Center Console & Hand Brake Pic:</p>